

## SKB TR-14-10

### Data report for the safety assessment SR-PSU

In the earlier distributed report, there are errors that now have been corrected. The changes are listed in the table below. An updated pdf version of the report, with the table printed on the back of the title page, can be found at [www.skb.se/publications](http://www.skb.se/publications).

#### Updated 2015-10

Location	Original text	Corrected text
Page 42, Section 4.4, first sentence	...inventory report (SKB 2013)...	...inventory report (SKB 2013, SKBdoc 1481419 (Mo-93))...
Page 42, Table 4-2, new reference		SKBdoc 1481419. Ny beräkning av Mo-93 i normkolli till PSU 2015-05
Page 43, first sentence	...inventory report (SKB 2013) and the calculated...	...inventory report (SKB 2013), except data sets for Mo-93 that are taken from SKBdoc 1481419, and the calculated...
Page 43, Table 4-3, new row inserted		SKBdoc 1481419
Page 44, Table 4-4, row Mo-93		This row is deleted
Page 44, Table 4-4, reference column, row Ni-59, Ni-63, Tc-99, I-129 and Cs-135	Cronstrand 2007	SKBdoc 1393443
Page 46, Figure 4-1		Figure updated
Page 46, figure text	KKV	NPP
Page 48, last paragraph	...each waste type (SKB 2013)...	...each waste type (SKB 2013, SKBdoc 1481419 (Mo-93))...
Page 49, Table 4-6	Wrong data in table	Table updated with correct data
Page 175, updated reference	1427105 ver 1.0	1427105 ver 4.0
Page 175, new reference		SKBdoc 1400742 ver 2.0. Kontroll av SFR-avfall. Delprojekt mätteknik. (In Swedish.) Gammadata mätteknik AB, 1990
Page 175, new reference		SKBdoc 1481419 ver 1.0. Ny beräkning av Mo-93 i normkolli till PSU 2015-05 (In Swedish.) SKB, 2015

#### Svensk Kärnbränslehantering AB

Swedish Nuclear Fuel  
and Waste Management Co  
Box 250, SE-101 24 Stockholm  
Tel +46 8 459 84 00

